| COMPLIANCE KPIs, 04 JULY 2023 | | | | | | | | |
|------------------------------------------------|------------|------------------------------------------------------------------------------------------------------------------------|-----------------------|---------------|---------------------|------------------|---|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Compliance Area | Pl Code | Performance Indicator | Risk | Target Number | Number Compliant | Total Overdue | | Management Comment |
| Asbestos | BS03 | Number of blocks & communal areas with a valid asbestos inspection (Yearly) | | 143 | 143 | 0 | • | We have 143 communal areas that require an asbestos inspection annually. |
| | ET01(a) | Number of properties with a valid electrical inspection certificate (EICR - 5 yearly) | | 4176 | 3509 | 667 | • | We have 4, 176 properties that require a 5 yearly electrical inspection; we have completed 3509 & 667 are outside the 5 year period. |
| | ET01(b) | Category 1 & Category 2 actions arising from an unsatisfactory EICR (residential dwellings) | | | | | | We had 31 Category 1 actions and all of these have been completed at the point of testing. |
| Electrical Systems (contracted maintenance) | | | C1 (point of test) | 31 | 31 | 0 | • | |
| | | | C2 (urgent) | | (5%) | 2078 | • | Following a thorough data validation we currently have a backlog of repairs from Covid & no accesses. We engaged an external consultant to review all the EICR's for Years 4 & 5 & are about to embark on a contract to clear these with the completion date for all outstanding repairs by December 2023. Weekly monitoring has been set up by the Compliance & Cyclical Servicing Manager & the Assistant Director for Housing. The Dodd Group have commenced testing & as such the number of C2's outstanding will reduce. |
| | ET02(a) | Number of distribution boards in communal areas with a valid electrical inspection certificate (EICR - 5 Yearly) | | 160 | 157 | 3 | • | We have 160 communal areas requiring inspection and have completed 157 with 3 outstanding and overdue. These are due to be completed by 31st July 2023. |
| | ET02(b) | Category 1 & Category 2 actions arising from an unsatisfactory EICR (communal areas) | C1 (point of test) | 0 | 0 | 0 | • | We had zero Category 1 actions. |
| | | | C2 (urgent) | | | 49 | • | The outstanding repairs have been issued to our term contractor to complete these are ordered and are in hand. |

| Fire Risk Assessment | BS02(a) | Number of blocks & communal areas with a valid fire risk assessment (Yearly) | | 143 | 143 | 0 | • | All Fire risk assessments are in place for all communal areas, community centres & district offices. We have just commissioned a new round of Fire Risk Assessments. |
|------------------------------------------------------|---------|-------------------------------------------------------------------------------------|-------------------------|------|-----------|-----|---|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | High | 6 | 6 | 0 | • | We have no outstanding high risk items |
| | BS02(b) | Actions arising from fire risk assessments | Medium | 716 | 418 | 298 | • | New round of fire risk assessments has commenced & scheduled to complete by 30th September 2023 Issues relating to doors will be identified as part of our fire door inspection regime, findings assessed & remedial/replacement works will be delivered either via the fire door inspection programme or through a planned works upgrade programme. One planned works project is currently on site & due to complete by end of July 2023 which will address a number of the issues & further planned works to capture the remaining actions/works will be implemented. We work closely with Devon & Somerset Fire & Rescue Service & who have reviewed our position & have verified & agreed our approach to address the issues identified. |
| | | | Low (Recommedations) | 438 | 252 | 186 | | The recommendations primarily relate to doors which are being addressed as part of our overarching fire door inpsection: signage is currently being addressed by the provision of new updated signs: items defined as recommendations are being addressed by future upgrade programme works in line with timescales discussed with Devon & Somerset Fire & Rescue. |
| Fire Protection Systems (contracted maintenance) | FP01 | Number of domestic fire doors with a valid inspection | | | 22 | 0 | • | We have one inscope building which is generally 4 stories with a small section deemed as being 5 story - therefore in scope. There are 22 flat front entrance fire doors which have all been inspected. All flats have fire doorsets fitted that were compliant with legislation |
| | FP02 | Number of communal fire doors with a valid inspection. | | | 12 | 0 | • | We have one inscope building which is generally 4 stories with a small section deemed as being 5 story - therefore in scope. We are within target |
| Gas Safety (contracted maintenance) | BS01 | Number of homes that have a valid gas safety check (LGSR) | | 3134 | 3134 | 0 | • | Within target |
| Lifting Equipment (contracted maintenance) | BS05 | Number of blocks with a valid lift inspection certificate (LOLER) | | 7 | 7 (5%) | 0 | • | Within target |
| Smoke & Carbon Monoxide Alarm Regulations 2022 | SM01 | Number of properties with a co detector (in development) | | 3291 | 3291 | 0 | • | We have 3291 properties which require a CO detector, all properties have adequate detection installed. |
| | SM02 | Number of properties with a smoke detector (in development) | | 4176 | 4176 | 0 | • | We have 4176 properties which require smoke detection, all properties conform to a minimum LD3 Standard. |
| Water Management (contracted maintenance) | BS04 | Number of blocks & communal areas that have a valid 4 legionella risk assessment | | | 21 | 0 | • | Within target |